

AC Drive Motor Rumbling / RPM Sensor Gap

Treadmills with an AC Drive Motor

If an AC drive motor is making a rumbling sound and has a jerky motion, check the gap between the RPM sensor and the tach wheel. The gap must be at least 2mm. When the gap between the sensor and the tach wheel is less than 2mm, it may give the symptoms of a faulty drive motor.

